

APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name: HM Tongeren
Make: RENAULT
Model / version: KANGOO EXPRESS
Vin: VF1WF000267081137
Plate: 2ARJ249
Mileage: 34957
First registration: 21/06/2021
Color:


ADDITIONAL INFORMATION






Category:
Transmission: Front
Interior color:
Metallic paint: ?
Type of lining:
Board computer reset: ✓

DOCUMENTS

Certificate of conformity: ✓
Registration certificate: ✓
Registration certificate 2: ✓
Insurance certificate: ?
Maintenance book:
Number of keys: 2
Original key: ✓

PICTURES





VIN INFORMATION

EQUIPMENT

Board computer: ?
 Compressor: x
 Gps: ?
 Rear parking sensor: ?
 Front seats heated: ?
 Electric windows: ?
 Headlighting type: ?
 Charging cables: 0

Central locking: ?
 Cruise control: ?
 Power steering: ?
 Repair kit: x
 Steering wheel: ?
 Climate control type: ?
 Tow bar type: ?
 Fast charging cables: 0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	4 mm			Winter		?
Front right	4 mm			Winter		?
Rear left	4 mm			Winter		?
Rear right	4 mm			Winter		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Step L	Grooved
2	Door FL	Dent(s) and scratch(es)
3	Wing RL	
4	Outside rear-view mirror housing L	Damaged
5	Rear light R	Crack
6	Wing RR	Dent(s) and scratch(es)
7	Wing trim RR	Missing
8	Door RR	Dent(s) and scratch(es)
9	Wing FR	Dent(s) and scratch(es)

Total: 9

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
No damages present					

DAMAGES DETAILS

1 - Step L - Grooved



2 - Door FL - Dent(s) and scratch(es)



3 - Wing RL



4 - Outside rear-view mirror housing L - Damaged



5 - Rear light R - Crack



6 - Wing RR - Dent(s) and scratch(es)



7 - Wing trim RR - Missing



8 - Door RR - Dent(s) and scratch(es)



9 - Wing FR - Dent(s) and scratch(es)



SIGNATURE

Expert

23/03/2026 13:49

CV