

APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name: HM Tongeren
Make: RENAULT
Model / version: KANGOO EXPRESS
Vin: VF1WF000668100069
Plate: 2BGC112
Mileage: 42984
First registration: 10/11/2021
Color:



ADDITIONAL INFORMATION









Category:
Transmission:
Interior color:
Metallic paint: ✖
Type of lining:
Board computer reset: ✖

DOCUMENTS

Certificate of conformity: ✔
Registration certificate: ✔
Registration certificate 2: ✔
Insurance certificate: ?
Maintenance book:
Number of keys: 2
Original key: ✔

PICTURES





VIN INFORMATION

Radio
 6 rapports
 Porte latérale droite coulissante
 Portes de chargement arrière vitrées
 Novembre
 Matière : tôle
 Diamètre arrière 15
 Diamètre avant 15
 Hauteur arrière 65
 Largeur avant 195
 Diamètre 15
 1461 cm3
 95 ch
 Unie vernissée
 Rétroviseur droit à réglage électrique
 Siège avant gauche réglable en hauteur
 Aide au stationnement arrière
 Lève-vitres avant électriques
 Programme électronique de stabilité ESP
 masque de phares 2

Radio avec système de navigation
 Porte latérale gauche coulissante
 Porte latérale droite vitrée
 3 081 mm
 Essuie-lunette arrière
 Lettre repère (J)
 Largeur avant 6,0
 Diamètre arrière 15
 Indice de vitesse avant T
 Largeur arrière 195
 Accoudoir central avant
 1.50 litre
 Euro 6
 Freins arrière à disques
 Rétroviseur gauche chauffant
 Siège avant droit rabattable
 Equipement Stop & Start
 Lunette arrière chauffante
 Antipatinage ASR / ASC+T
 boîte à gants avec couvercle

Boîte manuelle
 Porte latérale gauche vitrée
 Fourgon tôle
 2020
 Code équipement EA1
 Diamètre avant 15
 Largeur arrière 6,0
 Hauteur avant 65
 Indice de vitesse arrière T
 Roue de secours tôle
 Diesel
 70 kw
 Filtre à particules
 Rétroviseur gauche à réglage électrique
 Rétroviseur droit chauffant
 Garnitures simili-cuir
 Verrouillage centralisé
 Vitre latérale fixe (rang2)
 Contrôle pression des pneus
 vide-poches au dessus du pare-brise

cloison de séparation grillagée et pivotante

EQUIPMENT

Board computer:	?	Central locking:	?
Compressor:	✖	Cruise control:	?
Gps:	?	Power steering:	?
Rear parking sensor:	?	Repair kit:	✖
Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	0	Fast charging cables:	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm			All-seasons	Steel	?
Front right	5 mm			All-seasons	Steel	?
Rear left	5 mm			All-seasons	Steel	?
Rear right	5 mm			All-seasons	Steel	?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Side wall RR	Scratch(es)
2	Door FR	Dent(s) and scratch(es)
3	Wing RL	Dent(s) and scratch(es)

Total: 3

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
No damages present					

DAMAGES DETAILS

1 - Side wall RR - Scratch(es)



2 - Door FR - Dent(s) and scratch(es)



3 - Wing RL - Dent(s) and scratch(es)



SIGNATURE

Expert

10/03/2026 11:04